Priority #	<u>Project Title</u>	Estimated Cost	Description of Project / Repairs
1121	Auxiliary Library Facility HVAC	\$113,860	Auxiliary Library Facility Upgrade HVAC- Currently under construction
1122	A ST. AND ST. AND ST. CASERY	4204.022	Upgrade fire alarm system and notifiers to include audible and visual
1123	Auxiliary Library Facility LIFE SAFETY Auxiliary Library Facility ROOF/BUILDING ENVELOPE		components Coat metal roof to add additional 20 year warranty
1123	Library Storage HVAC (tin building)		Replace small AHU unit
1124	Library Storage LIFE SAFETY (block building)		Needs Fire safety upgrade
1125	Library Storage LIFE SAFETY (tin building)		Needs Fire safety upgrade
1128	Library Storage ROOF/BUILDING ENVELOPE (block building)		Coat metal roof to add additional 20 year warranty
	Elstary storage moory socies in a circles in a circle	Ų01,320	Coat metal roof and possibly exterior walls to add additional 20 year
1126	Library Storage ROOF/BUILDING ENVELOPE (tin building)	\$51,990	warranty
	(,	Upgrade fire alarm system and notifiers to include audible and visual
203	LIBRARY WEST FIRE ALARM DEVICES REPLACEMENT	\$1,678,700	components
892	Library West HVAC	\$131,922	Replacement of AHU
893	Library West LIFE SAFETY	\$11,433	Upgrade fire alarm panel
894			Repair and seal addition exterior masonry, repair/replace/caulk windows,
	Library West ROOF/BUILDING ENVELOPE		and repair facia stone and soffit. Repair/replace roof and any flashings
503	Marston Science Library HVAC	\$909,199	Replace remaining HVAC units
504			Upgrade fire alarm system and notifiers to include audible and visual
	Marston Science Library LIFE SAFETY	\$688,791	components
505			Upgrade building plumbing pipes (This information is based off ISES Facility
	Marston Science Library PLUMBING	\$55,444	Condition assessment and costs need to be revisited)
160			Replacement of HVAC air handling units 1-8 based on age of units. Some
100	MARSTON SCIENCE LIBRARY REPLACE 8 AHU UNITS (1-8)	\$1.085.600	units may not have to be replaced based on age and/or condition
	WINISTON SCIENCE EIDINANT NEFENCE 8 AND ONTS (1-6)	71,063,000	units may not have to be replaced based on age and/or condition
109			
103	MARSTON SCIENCE LIBRARY REPLACE GENERATOR	¢194 700	Replace generator due to age of the unit.
	IVIANSTON SCIENCE LIBRART REPLACE GENERATOR	\$104,700	neplace generator due to age of the drift.
506			Repair and seal exterior masonry, repair/replace/caulk windows, and repair
	Marston Science Library ROOF/BUILDING ENVELOPE	\$639 950	facia stone and soffit. Repair/replace roof and any flashings
3	SMATHERS LIBRARY COMPLETE HVAC REPLACEMENT-ENGINEERING COMPLETED		Replace HVAC unit on the first floor, shovel ready
		¥:=:,000	Repair and seal exterior masonry, repair/replace/caulk windows, and repair
104	SMATHERS LIBRARY COMPLETE MASONARY, WINDOW WATER REPAIR AND PREVENTION	\$1,678,700	facia stone and soffit
396	Smathers Library HVAC	\$286,984	Replace 4th floor HVAC system on the south end.
397			Upgrade fire alarm system and notifiers to include audible and visual
397	Smathers Library LIFE SAFETY	\$711,427	components
398			Upgrade building plumbing pipes (This information is based off ISES Facility
330	Smathers Library PLUMBING	\$27,333	Condition assessment and costs need to be revisited)
251			Historic roof replacement which requires removal, number, and catalog
			existing roof tiles, replace roof underlayment, reuse historical tiles that are
	SMATHERS LIBRARY REPLACE TILE ROOF	\$1,902,600	not damaged and replace ones that are unusable.
200			5
399	Smathars Library BOOF / BUILDING ENVELORE	¢1 264 502	Repair and seal addition exterior masonry, repair/replace/caulk windows,
	Smathers Library ROOF/BUILDING ENVELOPE	\$1,364,583	and repair facia stone and soffit. Repair/replace roof and any flashings
TOTAL		\$14,657,655	
IOIAL		714,037,033	